

PHENIX WEEKLY PLANNING

9/7/06 Don Lynch

PHENIX Shutdown Overview



Technica

Support

2006

Task_Name	Start_Date	Finish_Date
PHENIX Shutdown '06	5/1/2006	12/8/2006
Pre Shutdown Tasks	5/1/2006	DONE
End of Run 6	6/27/2006	DONE
Shutdown Preparations	6/27/2006	DONE
Detector Upgrades	7/19/2006	10/10/2006
Planned electrical power outage	7/24/2006	DONE
Subsystem maint/repair tasks	7/19/2006	10/10/2006
Building and infrastructure tasks	5/1/2006	10/31/2006
		404044000
E carriage roll in & setup	10/11/2006	10/31/2006
RHIC Cooldown Begins	11/1/2006	11/1/2006
Run Prep	11/22/2006	12/8/2006
Chutdaus Canaludad Ctart Dhusian Dus	40/0/000	40/0/000
Shutdown Concluded Start Physics Run	12/8/2006	12/8/2006





Prior To Shutdown







Shutdown Prep

Shutdown Preparations

Purge gas from all detectors End of Run party

DAQ tests (no Flam. Gas)

Open up & prep

Open rolling door

Remove rolling

Take down E

Prepare EC fo

Remove bear

Move MMS fu h and re

Retract and re

Install 12 ton

Move beampi

Install decking









16 days 6/26/2006 2 days Done

Done

Done Done Done

7/18/2006

Done Done Done

Done Done

Done









TOF West	-	-
Design	Done	Done
Purchased/procured parts	Done	Done
Fabricated parts	Done	Done
Assembly at 510	Done	Done
Work permit	Done	Done
Mechanical Installation	Done	Done
PHENIX mechanical survey offsets (adjustments completed no further adjustment reasonably feasible)	Done	Done
Electrical	-	-
HV/LV/Signal Cable routing & connecting	Done	Done
Modify/upgrade rack	-	-
electronics	18-Jul	15-Sep
cooling water	18-Jul	15-Sep
Testina	18-Jul	15-Sep













RXNP (Cont'd)

Electrical Installation

Electron insulation		
HV/signal/optical routing and connecting	Done	Done
Rack installation	-	-
Mechanical Installation	Done	Done
Water hookup	5-Sep	8-Sep
Power hookup	5-Sep	8-Sep
Cable connections	5-Sep	8-Sep
Safety systems	4-Sep	8-Sep
Grounding	5-Sep	8-Sep
Testing	31-Aug	1-Oct
Project Closeout	27-Oct	1-Dec








Technica Support 2006

HBD	-	-
Design	Done	Done
Purchased/procured parts	Done	Done
Fabricated parts	Done	Done
Assembly	-	-
West and East detectors at Stony Brook	18-Jul	2-Oct
electronics racks at PHENIX	Done	Done
cable trays at PHENIX	Done	Done
movable cable trays	Done	Done
Fixed cable trays	Done	Done
Pre-Survey: West and East detectors at Stony Brook	-	-
West detector	Done	Done
East detector	18-Sep	6-Oct
Scribe centerline marks on upper and lower ibeams	Done	Done
Mechanical Installation: West and East detectors in IR	-	-
West detector	Done	Done
East detector	20-Sep	9-Oct
West moveable cable trays	5-Sep	8-Sep
East moveable cable trays	25-Sep	10-Oct



Fixed cable trays

Done

Done



Technical

Support 2006

Detector Upgrades

HBD

Installation survey	-	-
Set up equipment for West detector	Done	Done
Adjust location of West detector	6-Sep	7-Sep
Set up equipment for East detector	27-Sep	9-Oct
Adjust location of East detector	28-Sep	10-Oct
Electrical Installation		
HV/signal/LV routing and connecting	11-Sep	11-Oct
Rack installation and connection	1 Sep	8-Sep
Mechanical Installation	Done	Done
Water hookup	8 Sep	8-Sep
Power hookup (Mike Rau)	8 Sep	8-Sep
Cable connections	8 Sep	22-Sep
Safety systems	8 Sep	22-Sep
Grounding	8 Sep	22-Sep
Testing	9-Sep	10-Oct
Gas system	-	-
Final piping	1 Sep	10-Oct
IR distibution panel and monitoring hardware	1 Sep	10-Oct
Gas house controls and monitoring system	1 Sep	31-Oct
Monitoring hutch controls, monitoring and piping	1 Sep	10-Oct
Other: Cooling, Heating, Flash Lamp: design/review/fabrication/installation	30-Aug	10- Oct





HBD Installation



More pictures of the HBD installation and design/construction/assembly/testing history can be found at

http://picasaweb.google.com/hadronblind





HBD Electronics Cooling

Tec h n C a S u p p 0 r



Needed for Approval to Operate:

- max HBD electronics temp on cooling failure (68 C)
- Consequences of failure presumed reduced preamp life if failure is allowed to continue
- Interlocks? No failure is not a safety concern only a longevity concern
- Where will fan(s) be mounted? CM base "cubby hole" fan model and specs to be forwarded to Safety
- Fan Filter? Effect on fan- Yes, on fan inlets, less than 5 in H2O dP
- Written installation & operation procedure To be forwarded to Safety



HBD Heaters



Needed for Approval to Operate:

- Heater Specs 6 MINCO non-magnetic kapton laminate heaters per detector, 17.6 ohms per heater (2 shown, 2 each on ends) Spec sheets to be supplied to Safety
- Peak current/Voltage/Power 70 watt peak power 35 Volt/2 amp peak (per heater)
- max temp at continuous peak operation (temperature controller failure) - 60 C
- Max controlled temperature 53 Cmonitored by RTD's
- Interlocks? RTD's for temperature control, power supply limits for power. Specs to be provided to Safety
- Heaters must be locked out during run? Yes or justification/impact to be forwarded to Safety
- Written installation & operation procedure To be forwarded to Safety



MPC N

Detector Upgrades

Technica Support

MPCN			
Design		Done	Done
Purchased/procured par	ts	Done	Done
Fabricated parts		-	-
Detector Parts	\$	Done	Done
Go-No Go gau	ige	Done	Done
Assembly		-	-
Pre assembly/f	it up at UI	Done	Done
Pre assembly/f	fit up at PHENIX	Done	Done
electronics rac	ks at PHENIX	11-Sep	15-Sep
Mechanical Installation			
Detector sexta	nts	11-Sep	12-Sep
cable trays		13-Sep	14-Sep
Installation survey		15-Sep	15-Sep
Electrical Installation			
TTT 7/ : 1/T T 7	and the second s	40.0	00.0



uon survey	15-5ep	15-Sep
eal Installation		
HV/signal/LV routing and connecting	18-Sep	22-Sep
Rack installation and connection	25-Sep	29-Sep
Mechanical Installation	25-Sep	29-Sep
Power hookup	25-Sep	29-Sep
Cable connections	25-Sep	29-Sep
Safety systems	25-Sep	29-Sep
Grounding	25-Sep	29-Sep



Testing

Project Closeout

2-Oct

27-Oct


10-Oct

1-Dec



MPC N at BNL





MPC N Rack goes here oriented with long edge vertical

18" cable tray has been replaced with 6" tray shifted 12" to the north on this face of MUID rack



Subsystems

h nica DC Suppo r t PC

IV. Existing Detector Maintenance **EMCal** WC maintenance and repair EC maintenance& repair

Done Done

Done Done

HV/LV patch panel Done Done West Wire repairs 18-Sep 22-Sep

MuTr

Prepare work permits for MMS and MMN Done Done Remove SE vertical lampshade Done Done Remove SE bias lampshade Done Done Troubleshoot shorts in MMS Done Done Repair shorts Done Done



Troubleshoot and repair Repair MMS and MMN HV/FEE's etc. Done Done Reinstall SE bias lampshade Done Done Reinstall SE vertical lampshade Done Done Closeout workpermit 9-Oct 9-Oct

Prepare Cables, modules 11-Oct 23-Oct HV Module and cable maintenance 24-Oct 31-Oct



Subsystems (continued)


Technica Support 2006

IV. Existing Detector Maintenance

Reinstall BBC North

Reinstall BBC South

MPC S	5		
	Prepare work permit	Done	Done
	Remove cables for access	Done	Done
	Remove top 2 octants for rework	Done	Done
	Rework/repairs on removed octants	Done	Done
	Reinstall top octants	Done	Done
	Reinstall wiring	Done	Done
	Closeout work permit	9-Oct	9-Oct
TEC			
	Machine slots in fittings	Done	Done
	Maintenance and repairs on TEC electronics	31-Jul	15-Sep
BBC			
	Remove BBC South and	Done	Done
	Remove BBC North	7-Sep	8-Sep
	Maintenance and repairs	23-Aug	22-Sep





MuID

25-Sep

26-Sep

30-Oct

25-Sep

26-Sep

3-Nov



Infrastructure Work

p

CAD/RHIC PHENIX infrastucture related mechanical and electrical support

Emergency remote breaker installation Done

Summer Sunday review platform and safety rails Done

Bridge Water supply vertical piping rework Done

Replace emergency fan louvres

Rewire/Add IR ceiling lights on emergency power

Replace WC sliding platform hoisting cables

Mixing House exhaust fan maintenance


Raw materials storage container painting and doors

Roof leak repairs

He Bags

MuID survey

Bridge protective runners



Done Done

one Done

-

- -

-

Done Done

-

1-Aug 31-Oct

2-Oct 6-Oct

Done Done









Infrastructure Work







He Bags













2006 Shutdown Wrapup/Run 7 Prep

East carriage roll in & setup

Prepare EC for move to IR	11-Oct	13-Oct
EC Roll in	16-Oct	17-Oct
Connect EC services	18-Oct	24-Oct
Install EC Ladder	24-Oct	25-Oct
Install EC rear access & ext.	25-Oct	26-Oct
Move MMS full North	26-Oct	26-Oct
Install beam pipe collar	27-Oct	27-Oct
Rebuild Rolling door	30-Oct	1-Nov
RHIC Cooldown Begins	1-Nov	1-Nov
RHIC Cooldown Begins Close rolling door	1-Nov 1-Nov	1-Nov
Close rolling door	1-Nov	1-Nov
Close rolling door Pink Sheeting & Blue Sheeting	1-Nov 1-Nov	1-Nov 21-Nov
Close rolling door Pink Sheeting & Blue Sheeting Start Flammable Gas Flow	1-Nov 1-Nov 22-Nov	1-Nov 21-Nov 22-Nov
Close rolling door Pink Sheeting & Blue Sheeting Start Flammable Gas Flow All Up Commissioning	1-Nov 1-Nov 22-Nov 27-Nov	1-Nov 21-Nov 22-Nov 1-Dec
Close rolling door Pink Sheeting & Blue Sheeting Start Flammable Gas Flow All Up Commissioning Beam in yellow ring	1-Nov 1-Nov 22-Nov 27-Nov 22-Nov	1-Nov 21-Nov 22-Nov 1-Dec 22-Nov



Next Week

Tec hnica Support 2006

- HBD west cable installation to bridge and to LV/signal rack, cooling & heating systems
- · Move CM South
- RXNP Crate wiring and electrical tests
- TEC repairs
- · BBC N removal for maintenance
- Begin MPC N installation
- MPC N Cable path/trays
- · MuTr N maintenance
- Move CM North for DC repairs

PHENIX

Tier I Concerns

1. Flammable material in the tech shop stored in boxes should be placed in the chemical cabinet We will investigate and address this issue as appropriate.

- 2. The following housekeeping issues must be corrected:
 - a. Boxes stored in the tech shop must be emptied and stored properly.

These are components for new detectors about to be installed. Their current location is proper and appropriate as a temporary location out of the way of current work in the IR until they are needed. No action required. Boxes will be discarded properly after contents are installed.

- b. Storing material between the building and shielding (Electronics Area) is not considered a storage area and should be removed.
- c. Storing gas tanks and holders under the wood steps outside is not allowed and should be removed.

We will investigate and address this issue as appropriate.

d. Cardboard on floor behind PHENIX experiment should be removed.

We will investigate and address this issue as appropriate.

e. 1008F wiring found outside and should be relocated.

We will investigate and address this issue as appropriate.

3. The PHENIX facility has numerous 4" openings that are not in compliance with OHSA standard. The standard allows 4" holes but not openings that are 4" wide by 8 - 10 feet long. All of the grating system needs to have fillers placed in these large openings

These openings are necessary for maneuvering the large detectors and our 12 ton cart. All unnecessary openings have already been addressed by the upgraded grating system installed by C-A during the 2005 shutdown. Bridging the gaps with fillers places an unnecessary burden on the PHENIX technical staff to continuously fill and unfill these gaps as equipment needs to move along the rails. PHENIX does not agree with the tier I findings on this issue and will not take any further action to address the findings.

Tier I Concerns



Technica I

Support 2006

4. In the PHENIX highbay area there is a sink and water pump in front of a disconnect that needs to be relocated per OHSA

Movement of the sink and water pump is a facilities issue that has previously been brought to the attention of the (C-A) facility manager. It will be addressed on a priority basis by C-A.

5. The PHENIX laser is not secured. A key was left in the power supply and the door is open. Remove the laser key and secure the area as required.

The tier 1 finding is incorrect. This has previously been addressed by PHENIX and C-A safety wherein it has been agreed that the laser is secured by lock within the laser enclosure and not by locking the room. The required safety/security procedure is and has been followed.

The PHENIX gas storage facility has three (3) small isobutene cylinders not secured. A gas storage sign is on the ground. Also a gas cylinder rack is all rusted (behind the carbon dioxide dewar) that needs to be replaced. In addition, the 5,200 gallon dewar does not have a "label" on it identifying its contents

These issues are acknowledged and will be addressed promptly (by Oct. 18).

In the PHENIX gas storage facility there is a 5,200 gallon dewar that has a manufacturer plate on it stating that this dewar is rated and designed to hold hydrogen. However, it is believed that the content of this large dewar is nitrogen, which is 14 times the density of hydrogen. This dewar requires the manufacturer to supply legal documentation stating that it is capable of holding 5,200 gallons of nitrogen. This document must be provided to the C-AD ESH Coordinator.

This issue has been addressed by the C-A safety committee and demonstrated to the committee by test documentation and calculations that the dewar is adequately designed for liquid nitrogen. PHENIX will obtain appropriate documentation indicating the suitability of the subject dewar for its current service and make sure that the tank is appropriately labeled promptly (by Oct. 18).

6.



7.





Technica Sup p r + 2006

Where To Find PHENIX Technical Info

Links for the shutdown schedule as well as weekly planning meeting slides, long term planning, pictures, videos and other technical info can be found from the web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm